HARS SC 7-BEAUE

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

Dr. Joseph Johnson House (Porter Danner House):
411 Craven Street
Beaufort
Beaufort County
South Carolina

HABS No. SC-187

Photo SC-187-1 was previously transmitted to the Library of Congress. The photos below were taken for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

PHOTO DATE: FEBRUARY 1979

SC-187-2 GENERAL VIE	W. SOUTH FRONT
----------------------	----------------

SC-187-3 GENERAL VIEW, FROM SOUTHEAST

SC-187-4 WEST SIDE, FROM SOUTHWEST

SC-187-5 EAST SIDE

SC-187-6 REAR VIEW, NORTH (left) AND WEST SIDES

SC-187-7 REAR VIEW, NORTH (right) AND EAST SIDES

SC-187-8 NORTH (REAR) SIDE, CENTRAL BAY.

No visible evidence of stairs at first floor door.

SC-187-9 FRONT PORTICO ELEMENTS: COLUMN CAPITAL AND CORNICE

SC-187-10 SOUTH (FRONT) PORTICO: TYPICAL JIB DOOR FROM SOUTHEAST AND SOUTHWEST ROOMS (2 each) ON FIRST AND SECOND FLOORS TO PORTICO

SC-187-11 FIRST FLOOR, HALL: MAIN DOOR FROM PORTICO AND TYPICAL DOOR (right) TO OTHER ROOMS

SC-187-12 FIRST FLOOR: NORTH STAIRHALL LOOKING WEST. Stair is a two-run open well.

SC-187-13 FIRST FLOOR, SOUTHEAST ROOM, NORTH WALL

SC-187-14 FIRST FLOOR, SOUTHEAST ROOM, NORTH WALL: MANTLE DETAIL.

The mantle is of earlier date than the house.

(continued)

DR. JOSEPH JOHNSON HOUSE Index To Photographs HABS No. SC-187 (page 2)

- SC-187-15 FIRST FLOOR, SOUTHEAST ROOM: CORNICE DETAIL. Southwest room cornice same.
- SC-187-16 FIRST FLOOR, SOUTHWEST ROOM, NORTH WALL
- SC-187-17 FIRST FLOOR, SOUTHWEST ROOM, NORTH WALL: MANTLE DETAIL. The mantle is of earlier date than the house.